

Overhead wires create visual clutter

The Kapahulu Liquor sign disrupts the roof parapet and is out of proportion with the building facade

The public pay phone adds clutter to the building facade

The roof parapet is discontinuous and undefined

The canopy, although a desirable feature, is in need of repair

The clutter of window display signs is unattractive and does little to attract customers



Overhead wires have been buried underground

Aesthetically graphic and dimensional signage has been added

The public pay phone has been removed from the building facade

The addition of a bold roof parapet and repeating panels under the display windows complements the horizontal feature of existing buildings in Kapahulu

The canopy, which is both decorative and functional, is repaired and maintained

The City's existing sign regulations are enforced and advertising of "low prices" no longer blocks the display windows

